

Inspection Photos
Location Name: Dakota Fee 1
API # : 067-06141



Corrective action completed, unused part removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dakota Fee 1
API #: 067-06141



Gear box leak and impacted material



Weeds growing up around equipment and near wellhead

Inspection Photos
Location Name: Dakota Fee 1
API #: 067-06141



Erosion from sheet flow and channeling from pad and on access road, looking north towards pad



Taken from further south looking north back towards pad

Inspection Photos
Location Name: Dakota Fee 1
API #: 067-06141



Access road eroded away, sediment migration onto and off road, no functioning erosion control BMPs



Erosion, sediment migration, no erosion control BMPs, road not designed or maintained properly for stormwater

Inspection Photos
Location Name: Dakota Fee 1
API #: 067-06141



Erosion off access road, looking south about half way to location



Erosion on access, no BMPs, looking north towards private road