

**Inspection Photos**  
**Location Name: Padgett 32-6 4-2**  
**Location ID: 333798**



**IMG 01**  
**Well sign**



**IMG 02**  
**Well sign**



**IMG 03**

**Lube oil has begun to impact material**



**IMG 04**

**Location overview**





**IMG 05**

**Lube oil has begun to impact material**



**IMG 06**

**Unused flowline risers not locked and tagged out**





**IMG 07**  
Unused equipment/debris



**IMG 08**  
Signs are deteriorating and capacity of tank on right now legible.



IMG 09

Debris near produced water tanks