

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2022

Submitted Date:

06/27/2022

Document Number:

702500119**FIELD INSPECTION FORM**Loc ID 436009 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1001 17TH STREET STE 1160City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Inspections@catamountep.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436010	WELL	PR	09/22/2014	CBM	067-09902	Campbell 33-7-4 1H	PR
436011	WELL	PR	09/16/2014	CBM	067-09903	Campbell 33-7-4 2H	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Emergency contact number listed on sign: 970-442-6620

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near wellhead (IMG 03). Unused 2" pipe near secondary containment (IMG 05), unused filters within secondary containment (IMG 04).		
Corrective Action:	Use or remove unused equipment/debris per rule 606.		Date: 07/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Location enclosed by barbed wire fence.		
Corrective Action:			Date:

Equipment:

Type: Gas Meter Run	# 2		corrective date
Comment:	Gas meter runs are located within separator house. Gas meter calibrations are up to date.		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	Separator vent stacks are screened properly.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:	4 marked rig anchors. 3 rig anchors are less than 4' in height (IMG 06).		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 07/09/2022

Type: Ancillary equipment	# 2	
Comment:	Telemetry, filter located inside secondary containment for produced water	
Corrective Action:		Date:
Type: Flow Line	# 8	
Comment:	2 4" lines from wellheads to separators, 2 1" lines from wellhead to prime mover generators, 2 4" lines from separators to off location, 2 2" lines from separators to produced water.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		37.128336,-107.600701
Comment:	Above ground steel produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	240 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Plastic jersey barrier perimeter with liner.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 436010 Type: WELL API Number: 067-09902 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 436011 Type: WELL API Number: 067-09903 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Waddles	Fail					
		Compaction	Pass			
Retention Ponds	Pass					Small rip rap retention pond
		Gravel	Pass			
Slope Roughening	Pass					
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					

Comment: Several wattles on west and north side of location are filled with sediment (IMG 07).

Corrective Action: Repair required BMPs per Rule 1002.f.(2)C

Date: 07/09/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500120	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789565