

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2022

Submitted Date:

06/27/2022

Document Number:

702500121**FIELD INSPECTION FORM**Loc ID 333339 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Kittinger, Eric | | ekittinger@mspartners.com | All SW field inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 298 | WELL | PR | 03/17/2010 | GW | 067-09494 | PADGETT 32-6 4-3 | PR |
| 273775 | WELL | PR | 01/05/2005 | CBM | 067-08976 | PADGETT 32-6 4-1 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Produced water tank NFPA signs are deteriorating and capacity is not legible (IMG 07 and IMG 08). | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 07/24/2022 |

Emergency Contact Number:

| | | | |
|--------------------|---|-------|--|
| Comment: | Emergency contact listed on well sign: 505-333-4869 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment near #4-3 wellhead (IMG 06). Unused equipment/debris near separator house (IMG 09). | | |
| Corrective Action: | Use or remove unused equipment per rule 606. | Date: | 07/09/2022 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--|-------|--|
| Type | OTHER | | |
| Comment: | Produced water tanks enclosed by wire fence. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Ancillary equipment | # 6 | | corrective date |
| Comment: | Telemetry, pump control panel, electric meter, electric panel, electric cabinet, produced water pump house. | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 6 | | |
| Comment: | 3 rig anchors marked properly. 3 rig anchors with markers less than 4' (IMG 04 and 05). | | |
| Corrective Action: | Install proper guy line markers per Rule 1003.a | Date: | 07/09/2022 |
| Type: Bird Protectors | # 4 | | |
| Comment: | Separators and tanks have vent stacks screened properly. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 15 | | |
| Comment: | In use: 1" line at produced water tanks, 2 2" lines from wellhead to separator, 2 4" lines from separator to gas meter run, 2 2" line and 2 1" line from separator to produced water, 2 3" lines from gas meter run to off location. Not in use: 2 1" lines at wellheads and 2 2" lines at wellheads. These lines are properly locked and tagged out. | | |

| | | | |
|---------------------------------|--------------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | Gas meter calibration is up to date. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | Bradenheads are accessible. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | 400 BBLS | STEEL AST | | 37.042320,-107.509404 | |
| Comment: | 2 above ground produced water tanks, each 400 bbl capacity. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------------|--|
| Condition | Adequate | |
| Other (Content) | Produced water | |
| Other (Capacity) | 400 bbl each | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 298 Type: WELL API Number: 067-09494 Status: PR Insp. Status: PR**Producing Well**Comment: Well free flowing at time of inspection, pump jack not in use.

Corrective Action:

Date:

Facility ID: 273775 Type: WELL API Number: 067-08976 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| | | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Culverts | Pass | | | |
| Slope Roughening | Pass | | | | | |
| | | Gravel | Pass | | | |
| Compaction | Pass | | | | | |

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 702500122 | photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789566 |