

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/21/2022

Document Number:

702800363

**FIELD INSPECTION FORM**Loc ID 313011 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
John Thomas		jthomas@rlbayless.com	
Neidel, Kris		kris.neidel@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
Helen Trujillo		notices@rlbayless.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
313011	LOCATION	AC			-	ZIMMERMAN/CHAMBERLIN-66N91W /4SWSE	RI

**General Comment:**

On 05/16/2022, Reclamation Specialist O'Malley conducted a reclamation and stormwater inspection at Robert L Bayless Producer LLC's Zimmerman/Chamberlin-66N91W /4SWSE Location #313011 in Moffat County, Colorado. This is also a follow up inspection to #702800200 and FIR Resolution #403076630

The following compliance issues were observed during this inspection:  
- Storage of unnecessary equipment

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	<p>Previous inspection #702800200 observed equipment not used for production operations was observed on Location including 3 campers, 1 boat, 1 car, 5 trailers and 1 tractor. Inspector required Operator to comply with Rule 606 by 6/13/2022. Operator submitted FIRR #403076630 stating CA Completed "Equipment mentioned belongs to landowner and well pad located next to private land. We cannot tell him not to put his personal equipment on his personal land."</p> <p>It was observed in this inspection that the previously observed equipment is present on Location. Per Rule 606.a. It is the responsibility of the Operator to control their Location and keep it in compliance at all times. Original corrective action and date remain applicable.</p>		
Corrective Action:	Comply with Rule 606.	Date:	06/13/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Previous inspection #702800200 observed impacted soils adjacent to the pumpjack to the southwest and throughout the tank battery secondary containment. Operator submitted FIRR #403076630 stating CA Completed "PU leak tightened, connectors tightened, oily soils removed."

At the time of this inspection no stained soils were observed at the pumpjack or in the tank battery secondary containment. This corrective action has been addressed.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Wattles	Pass					

Comment: Previous inspection #702800200 observed insufficient stormwater and sediment control BMPs in place. Inspector required Operator to install or repair required BMPs per Rule 1002.f. 6/13/2022. Operator submitted FIRR #403076630 stating "filled eroded areas, added more wattles"

It was observed in this inspection that wattles have been reinstalled at the west of the Location. Wattles were shallowly trenched and backfilled with a small amount of sediment. Adjacent wattles were overlapping. This corrective action has been addressed, however, it is unclear if the wattles are sufficient to manage stormwater on the Location, as this control measure failed previously. Inspector suggests regular monitoring and maintenance of control measures.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403085955	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5785152">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5785152</a>
702800364	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5785151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5785151</a>