

Final Reclamation Inspection

May 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330982

Inspection Document #: 701900376

SENW Section 2 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 2. Overview photo of the well pad taken at ground level from the western edge looking east. Note: well pad resides in a fallow agricultural field and appears consistent with reference area.

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 3. Reference area to the north of the well pad.

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 4. Overview photo of the access road taken from the eastern edge looking west. Note: appears consistent with reference area.

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 5. Overview photo of the tank battery. Note: southern edge of the disturbance is dominated by kochia, musk thistle and hoary cress.

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 6. Hoary cress (left photo) and musk thistle (right photo) on southern edge of the tank battery.