

Resolved Photos – ALLISON UNIT 19M

05.067.08223

Today's Date:	5/26/2022					
Well Name:	ALLISON UNIT 19M	Location:	Sec: 24	Twn: 032N	Rng: 007W	UL: G
API Number:	05.067.08223	Footage:	2480' FNL & 2320' FEL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0509	Brian Van Caster	
Meter #:	7670701		Pipeline:	HAR		
INC Number:	693904555	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	6/30/2022	
Issue of Concern:	On 5/24/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed: -Control weeds. Due to the extent of the infestation a treatment plan is needed and multiple treatments will likely be needed. Seeding in treatment areas may be needed after infestation is controlled. Corrective action date: 6/30/2022					
	See below, and attached photos for additional detail.					
	Thousands of Russian knapweeds observed within the interim reclamation areas and along the western access road.					
	-Control weeds. Due to the extent of the infestation a treatment plan is needed and multiple treatments will likely be needed. Seeding in treatment areas may be needed after infestation is controlled. Corrective action date: 6/30/2022					

From: Patrick Hudman <phudman@hilcorp.com>
 Sent: Tuesday, June 28, 2022 4:34 PM
 To: Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>
 Subject: FW: ALLISON UNIT 19M - INC - 693904555

Russian Knapweeds have been sprayed. See pics.

Thanks

Patrick Hudman
 Area 5 Production
 505-320-1225









