

Today's Date:	5/26/2022					
Well Name:	ALLISON UNIT 19	Location:	Sec: 24	Twn: 032N	Rng: 007W	UL: K
API Number:	05.067.05008	Footage:	800' FSL & 1849' FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0509	Brian Van Caster	
Meter #:	7666401		Pipeline:	HAR		
INC Number:	693904551	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	6/30/2022	
Issue of Concern:	<p>On 5/24/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:</p> <p>- Close and reclaim reclamation areas impacted by vehicle traffic and educate personnel to avoid driving on reclamation areas in order to prevent site degradation. Corrective action date 6/30/2022.</p> <p>See below, and attached photos for additional detail.</p> <p>Vehicle tracking is occurring within the western reclamation area where multiple vehicle tracks are damaging vegetation. Revegetation is progressing within portions of the reclamation area where tracking is not occurring.</p> <p>- Close and reclaim reclamation areas impacted by vehicle traffic and educate personnel to avoid driving on reclamation areas in order to prevent site degradation. Corrective action date 6/30/2022.</p>					

From: Patrick Hudman <phudman@hilcorp.com>
 Sent: Wednesday, June 29, 2022 7:54 PM
 To: Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>
 Subject: FW: ALLISON UNIT 19 - INC - 693904551

Reclamation area has been closed with a fence and signs to prevent vehicle travel. See Pic.

Thanks

Patrick Hudman

Area 5 Production

505-320-1225



