

Today's Date:	5/26/2022					
Well Name:	ALLISON UNIT 25M	Location:	Sec: 19	Twn: 032N	Rng: 006W	UL: G
API Number:	05.067.08186	Footage:	2410' FNL & 2305' FEL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0509	Brian Van Caster	
Meter #:	7666701		Pipeline:	HAR		
INC Number:	693904549	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	6/30/2022	
Issue of Concern:	<p>On 5/24/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:</p> <p>-Treat and remove tamarisk tree on access road. Corrective action back-dated to original date: 6/1/2020 -Stabilization measures need to be conducted on the well pad to prevent deep tracking and stabilize driving surface. Additionally, operator needs to close reclamation areas to vehicle traffic and educate personnel to avoid driving on reclamation areas in order to prevent site degradation. Corrective action date 6/30/2022.</p> <p>See below, and attached photos for additional detail.</p> <p>Deep rutting (approx 12-18 inches) observed within the northern project area. Vehicle tracking observed within the reclamation area resulting. Both of these are resulting in site degradation.</p> <p>Tamarisk tree observed on the access road remains and needs to be treated/removed. Russian knapweeds were not observed at this time. Continued monitoring and management is needed to prevent re-establishment or spread of knapweeds. Revegetation is progressing within portions of the interim reclamation area where vehicle tracking is not occurring.</p>					

From: Patrick Hudman <phudman@hilcorp.com>
Sent: Wednesday, June 29, 2022 8:20 PM
To: Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>
Subject: FW: ALLISON UNIT 25M - INC

Tamarisk tree has been removed.

Signs and fencing installed to keep vehicles off reclaimed area

Location ruts have been filled in and repaired.

Thanks

Patrick Hudman

Area 5 Production

505-320-1225











