

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/23/2022

Submitted Date:

06/24/2022

Document Number:

702500114

**FIELD INSPECTION FORM**

Loc ID 325533 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10663  
Name of Operator: ENDURING RESOURCES LLC  
Address: 6300 S SYRACUSE WAY, SUITE 525  
City: CENTENNIAL State: CO Zip: 80111

**Findings:**

- 23 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	<a href="#">All SW field inspections</a>
Walker, Kyle		kwalter@enduringresources.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214959	WELL	PR	05/18/1994	CBM	067-06564	STATE-ROYCE 1-36	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment: Emergency contact located on well sign: 1-800-916-7897 or 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash north of separator (IMG 05), trash east of compressor (IMG 06), trash on west edge of location (IMG 07 and IMG 08).		
Corrective Action:	Remove trash to comply with rule 606.	Date:	07/01/2022

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Pump jack, separation equipment, produced water tank, and compressor are enclosed by stock panel.		
Corrective Action:		Date:	

**Equipment:**

Type	#			corrective date
Compressor	# 1			
Comment:	Compressor with lube oil. Lube oil has proper spill prevention and is screened with wire mesh as a wildlife BMP.			
Corrective Action:		Date:		
Ancillary equipment	# 2			
Comment:	Telemetry, pump control panel			
Corrective Action:		Date:		
Gas Meter Run	# 1			
Comment:	Gsa meter run is inside separator house. No meter calibration record present (IMG 04).			
Corrective Action:	Gas meter must be calibrated within the last year per rule 430.d.(1).		Date:	07/03/2022
		Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		
Bird Protectors	# 1			
Comment:	Separator vent stack is screened properly.			
Corrective Action:		Date:		
Prime Mover	# 1			
Comment:	Electric prime mover			
Corrective Action:		Date:		
Bradenhead	# 1			

Comment:	Bradenhead is accessible.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	4" line from wellhead to separator, 2" line from separator to produced water, 3" line stubbed up near separator.		Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	4 marked rig anchors.		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.248732,-107.799834
Comment:	Partially buried produced wter tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	Cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm secondary containment.			
Corrective Action:				
				Date:

**Venting:**

Yes/No		Date:
Comment:		
Corrective Action:		

**Flaring:**

Type		Date:
Comment:		
Corrective Action:		

**Inspected Facilities**

Facility ID: 214959 Type: WELL API Number: 067-06564 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Retention Ponds	Pass					Small rip rap retention pond on west side
Waddles	Fail					Multiple wattles around location are deteriorated.
Ditches	Pass					Ditches along west side
		Compaction	Pass			
Gravel	Pass					Location beginning to develop ruts.
		Gravel	Pass			
Ditches	Fail					Ditch along west side overtopped by run on
Rip Rap	Pass					Rip rap run off

Comment: [Multiple storm water controls present. Multiple wattles around location are deteriorated and not maintained \(IMG 09 and IMG 10\).](#)  
[Ditch along west end of location is overtopped and run on is entering location \(IMG 11\).](#)

Corrective Action: [Repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 07/09/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403089956	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789568</a>
702500116	Photo Doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789564</a>