

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2022

Submitted Date:

06/27/2022

Document Number:

702500121**FIELD INSPECTION FORM**Loc ID 333339 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298	WELL	PR	03/17/2010	GW	067-09494	PADGETT 32-6 4-3	PR
273775	WELL	PR	01/05/2005	CBM	067-08976	PADGETT 32-6 4-1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank NFPA signs are deteriorating and capacity is not legible (IMG 07 and IMG 08).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/24/2022

**Emergency Contact Number:**

Comment:	Emergency contact listed on well sign: 505-333-4869		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near #4-3 wellhead (IMG 06). Unused equipment/debris near separator house (IMG 09).		
Corrective Action:	Use or remove unused equipment per rule 606.	Date:	07/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Produced water tanks enclosed by wire fence.		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 6		corrective date
Comment:	Telemetry, pump control panel, electric meter, electric panel, electric cabinet, produced water pump house.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	3 rig anchors marked properly. 3 rig anchors with markers less than 4' (IMG 04 and 05).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/09/2022
Type: Bird Protectors	# 4		
Comment:	Separators and tanks have vent stacks screened properly.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		

Comment: Bradenheads are accessible.		Date:
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment: Gas meter calibration is up to date.		
Corrective Action:		Date:
Type: Flow Line	# 15	
Comment: In use: 1" line at produced water tanks, 2 2" lines from wellhead to separator, 2 4" lines from separator to gas meter run, 2 2" line and 2 1" line from separator to produced water, 2 3" lines from gas meter run to off location.  Not in use: 2 1" lines at wellheads and 2 2" lines at wellheads. These lines are properly locked and tagged out.		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		37.042320,-107.509404
Comment: 2 above ground produced water tanks, each 400 bbl capacity.					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	400 bbl each
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 298 Type: WELL API Number: 067-09494 Status: PR Insp. Status: PR**Producing Well**Comment: Well free flowing at time of inspection, pump jack not in use.

Corrective Action:

Date:

Facility ID: 273775 Type: WELL API Number: 067-08976 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
		Gravel	Pass			
Compaction	Pass					
		Culverts	Pass			
		Ditches	Pass			
Gravel	Pass					
		Compaction	Pass			
Ditches	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403089958	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789570</a>
702500122	photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5789566</a>