

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/28/2022

Document Number:

700600403

**FIELD INSPECTION FORM**Loc ID 324506 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcgee/Anadarko		COGCCInspections@Oxy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211866	WELL	PR	12/01/2020	CO2	055-06104	SHEEP MOUNTAIN UNIT 8 -2-P	EI

**General Comment:**

This is an environmental inspection only.

Unpermitted pit on location. See corrective action.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat: <u>37.646836</u>	Long: <u>-105.179428</u>
-------	--------	---------	-----------------------	--------------------------

Reference Point: <u>SE</u>	Other: _____	Length: <u>35</u>	Width: <u>25</u>
----------------------------	--------------	-------------------	------------------

**Lining:**

Liner Type:

Liner Condition:

Comment:

Unpermitted pit on location.

Corrective Action

Submit Form 15 to permit pit or submit Form 27 to close pit.Date: 07/31/2022**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403091516	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790839">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790839</a>
700600404	Pit photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790835</a>