

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2022

Submitted Date:

06/28/2022

Document Number:

702500125**FIELD INSPECTION FORM**Loc ID 333433 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215270	WELL	PR	10/05/2021	GW	067-06875	BUFORD WAYT A 1	PR
293705	WELL	PR	11/27/2007	CBM	067-09443	BUFORD WAYT A 3	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign is deteriorated (IMG 04).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/27/2022

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Partially buried corrugated pipe near A1 wellhead (IMG 03).		
Corrective Action:	Remove if not needed for ongoing operations per rule 606.	Date:	08/11/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Location enclosed by barbed wire fence.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pump jacks, separator, gas meter run, and produced water tank are enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:	Separator vent stacks are enclosed properly.		
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	2 3" and 2 2" lines from wellhead to separator, 2 lines from separator to produced water.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Telemetry, Electric panel and cabinet, electric meter, isolation valves.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are up to date.		
Corrective Action:		Date:	

Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.143739,-107.644471	
Comment:	Partially buried produced water tank.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)	Produced water	
Other (Capacity)	95 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	Metal secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 215270 Type: WELL API Number: 067-06875 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 293705 Type: WELL API Number: 067-09443 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403091294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790611
702500133	ohoto doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5790608