

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2022

Submitted Date:

06/29/2022

Document Number:

702500134**FIELD INSPECTION FORM**Loc ID 325012 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213816	WELL	PR	02/01/2022	GW	067-05082	SEVER 1	PR
476723	Domestic Tap	AC	06/03/2020		-	Domestic Tap 13SENE	AC

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Access road is both dirt and washed rock. Some sections of dirt road are developing ruts.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				Date:
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment and trash in spill prevention for oil container (IMG 03).			
Corrective Action:	Use or remove unused equipment per rule 606. Remove trash per rule 606.			Date: 07/13/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Produced water tank enclosed by wire fencing.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 5			corrective date
Comment:	In use: 2" line from wellhead to separator, 4" line from separator to gas meter run, 2" line from separator to produced water, 1" line to domestic tap. Not in use: 2" line stubbed up near gas meter run is not locked out/tagged out (IMG 04).			
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)			Date: 07/13/2022
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Meter calibration is up to date.			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Telemetry, Domestic tap in cabinet near wellhead, oil container.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			

Comment:	Separator vent stack screened properly.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.019343,-107.879554
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	gravel and dirt berm.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	213816	Type:	WELL	API Number:	067-05082	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:					Date:				
Facility ID:	476723	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403092503	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791838
702500135	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791833