

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2022

Submitted Date:

06/29/2022

Document Number:

702500136**FIELD INSPECTION FORM**Loc ID 326093 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs @hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215854	WELL	PR	02/02/1991	CBM	067-07459	CARTER UTE 107	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
Type	Access		
comment:	Dirt access road is developing ruts.		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Above ground produced water tank signs beginning to deteriorate (IMG 10).		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Impacted material at oil container north of compressor skid (IMG 07). Impacted material west of partially buried produced water tank (IMG 08). Impacted materail west of compressor skid (IMG 09).		
Corrective Action:	Remove impacted material per rule 906 and 1002.f.	Date:	07/13/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at wellhead (IMG 06). Unused equipment at southern separator (IMG 05).		
Corrective Action:	Use or remove unused equipment per rule 606.	Date:	07/13/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Produced water tanks are enclosed by wire fencing.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead		# 1	corrective date
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Flow Line		# 10	

Comment:	In use: 4" line from wellhead to separator, 1" line from separator to compressor skid, 3 1" lines to produced water tanks, 2" line from southern separator to partially buried produced water tank, 2" and 4" line at northern separator, 1" line at above ground produced water tanks.			
	Not in use: 2" line stubbed up near southern separator, with no lock out/tag out.			
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)			Date: 07/13/2022
Type: Gas Meter Run	# 1			
Comment:	Meter calibration is up to date.			
Corrective Action:				Date:
Type: Bird Protectors	# 5			
Comment:	Above ground produced water tanks and both separator vent stacks are screened properly.			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:	Compressor skid with metal roof.			
Corrective Action:				Date:
Type: Other	# 3			
Comment:	Oil containers. 2 oil containers do not have spill prevention (IMG 03 and 04).			
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.			Date: 07/13/2022
Type: Prime Mover	# 1			
Comment:	Gas powered			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Telemetry, cathodic protection, electric panel.			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.020918,-107.880493
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	120 bbl
Other (Type)	cone top

Berms

Inspector Name: Klink, Alex

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Gravel and dirt earth berm.					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	500 BBLS	STEEL AST		37.020577,-107.880284	
Comment: 3 above ground produced water tanks, each with 500 bbl capacity.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) 500 bbl		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Gravel and dirt earth berm.					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 215854	Type: WELL	API Number: 067-07459	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403092504	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791839
702500137	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791834