

Catamount Energy Partners
COGCC Inspection 702500119 Remedial Report
Work Completed 7/6/2022

- Comment: Unused equipment near wellhead (IMG 03). Unused 2" pipe near secondary containment (IMG 05), unused filters within secondary containment (IMG 04). Use or remove unused equipment/debris per rule 606.
Action Taken: 2" pump line & temporary fencing from Campbell 33-7-4#2H wellhead to separator removed. 2" pipe on north side of tank containment removed. Tubing rotator on Campbell 33-7-4#1H removed. Water filters removed from location
- Comment: 4 marked rig anchors. 3 rig anchors are less than 4' in height (IMG 06). Install proper guy line markers per Rule 1003.a
Action Taken: All rig anchors removed.



Removed tubing rotator



Removed Water filters



Removed unused 2" pipe

Catamount Energy Partners
COGCC Inspection 702500119 Remedial Report
Work Completed 7/6/2022

- Comment: Several wattles on west and north side of location are filled with sediment (IMG 07). Repair required BMPs per Rule 1002.f.(2)C
Action Taken: Wattles in disrepair surrounding location have been cleaned, replaced, and/or reset. Areas near wattles raked and hand reseeded.



North Edge of Pad



North Edge of Pad 2



NW Corner of Pad



South Edge of Pad



South Edge of Pad 2



SW Corner



West Edge of Pad