

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

702500195**FIELD INSPECTION FORM**Loc ID 325534 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214961	WELL	PR	07/01/1999	CBM	067-06566	MW JOHNSON A 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	All equipment at this location is enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	#		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry, pump control panel Equipment associated with A3 and A4 wells: Electric cabinet		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:		Date:	
Type: Vertical Heated Separator	#		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Compressor house is also associated with A3 and A4 wells.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	3" and 2" lines from wellhead to separator, line from separator to produced water, 4" line from gas meter run to off location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	1 rig anchor not marked (IMG 05).		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	07/22/2022
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	Separator vent stack is screened properly,			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.194581,-107.717460	
Comment:	Partially buried produced water tank.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	10 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Gravel and dirt earth berm secondary containment.				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 214961	Type: WELL	API Number: 067-06566	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
Ditches	Pass					
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					
Rip Rap	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500197	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797756