

# Inspection Photos

API: 061-06867

Operator: MULL DRILLING COMPANY INC

Inspection Date: 7/7/2022



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 1.** Facing northeast along the access road. There are areas where stormwater is pooling on the road causing vehicles to drive around and widen the road. This area needs to be stabilized with BMP's such as gravel. Stormwater should be diverted off the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 2.** Facing northeast along the access road. This area along the road is stabilized with gravel.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 3.** Facing northeast along the access road. There are areas where stormwater is pooling on the road causing vehicles to drive around and widen the road. This area needs to be stabilized with BMP's such as gravel. Stormwater should be diverted off the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 4.** Facing northeast along the access road. There are areas where stormwater is pooling on the road causing vehicles to drive around and widen the road. This area needs to be stabilized with BMP's such as gravel. Stormwater should be diverted off the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 5.** Facing north along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 6.** Facing west toward the well site. There is erosion occurring at the cattleguard that needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 7.** Facing southeast toward the location. The catwalk is tipped over and not in use and should be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 8.** Thee berms around the tank are inadequate and need to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022

## Inspection Photos



**Photo 9.** Thee berms around the separator are inadequate and should be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06867 | Date: 7/7/2022