

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2022

Submitted Date:

07/05/2022

Document Number:

702500162**FIELD INSPECTION FORM**Loc ID 326530 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89148	WELL	PR	03/20/2000	CBM	067-08252	HUBER-CROOK 4-26	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment under pump jack (IMG 03). Unused muffler north of pump jack (IMG 04).		
Corrective Action:	Use or remove equipment per rule 606.		Date: 07/19/2022
Type	OTHER		
Comment:	Lube oil in separator/gas meter run house is present on floor and has begun to impact surface material (IMG 05).		
Corrective Action:	Remove oily residue on floor, remove impacted material and dispose of in approved manner per rule 906 and 1002.f. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 07/19/2022
Type	TRASH		
Comment:	Trash near separator house (IMG 06).		
Corrective Action:	Remove trash per rule 606.		Date: 07/13/2022

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pump jack is enclosed on 3 sides by sound panel and stock panel on remaining side.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		

Comment:	Telemetry, pump jack lube oil, tracer wire conduit		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	1 rig anchor not marked (IMG 07).		Date:	
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	07/19/2022
Type: Gas Meter Run	# 1			
Comment:	Gas meter calibration is within the last year.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Flow Line	# 6			
Comment:	3" and 2" line from wellhead to separator, 3" and 2" line from separator to off location, 1" line from wellhead to generator, 1" line at separator house.		Date:	
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 89148	Type: WELL	API Number: 067-08252	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Ditches	Pass					
Berms	Pass					
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
		Compaction	Pass			
Compaction	Pass					
Check Dams	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403095693	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794709
702500163	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5794700