

Inspection Photos

June 29, 2022

Operator: Wyman* Louis M DBA Wyman Inc - #97730

Location ID: 313012

Location Name: Weco-UPRC Kleitz 23-29-67N92W
/29NESW

Inspection Document #: 702800386

Moffat County, CO

NESW Section 29 T7N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW

Location ID: 313012



Photo 1. Photo taken from the north of the Location shows an overview of the east of the Location.



Photo 2. Photo taken from the north of the Location shows an overview of the west of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800386

Inspection Photos

Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW

Location ID: 313012



Photo 3. Photo taken from the east of the Location shows the cut slope is bare and eroded. Undercutting is occurring, resulting in soil loss.



Photo 4. Photo taken from the east of the Location shows the unstabilized cut slope is undercutting. Note also, two metal poles remain on Location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800386

Inspection Photos

Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW

Location ID: 313012



Photo 5. Photo taken from the south of the Location at the start of Disturbed Transect 1 shows an overview of the transect. Note also, two tanks remain on Location.



Photo 6. Photo taken from the south of the Location at the start of Disturbed Transect 1 shows the ground surface.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800386

Inspection Photos
Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW
Location ID: 313012



Photo 7. Photo taken from the center of the Location at the end of Disturbed Transect 1 shows an overview of the transect.



Photo 8. Photo taken from the center of the Location at the end of Disturbed Transect 1 shows the ground surface.

Inspection Photos
Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW
Location ID: 313012



Photo 9. Photo taken in the reference area to the south of the Location at the start of Reference Transect 1 shows an overview of the transect.



Photo 10. Photo taken in the reference area to the south of the Location at the start of Reference Transect 1 shows the ground surface.

Inspection Photos
Location Name: Weco-UPRC Kleitz 23-29-67N92W /29NESW
Location ID: 313012



Photo 11. Photo taken in the reference area to the south of the Location at the end of Reference Transect 1 shows an overview of the transect.



Photo 12. Photo taken in the reference area to the south of the Location at the end of Reference Transect 1 shows the ground surface.