

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

693507516**FIELD INSPECTION FORM**
 Loc ID 318749 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242099	WELL	SI	11/01/2021	GW	123-09890	UPRR 43 PAN AM I 30	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	No visible road		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	08/07/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	Mechanical issue: Well head has small leak around tubing.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	07/08/2022
Type	WEEDS		
Comment:	Weeds on location and around well head.		
Corrective Action:	Comply with rule 606	Date:	08/07/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused electric line cut on locaiton		
Corrective Action:	Comply with rule 606	Date:	05/05/2022
Type	UNUSED EQUIPMENT		
Comment:	Cement pumping base		
Corrective Action:	Comply with rule 606	Date:	05/05/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 242099 Type: WELL API Number: 123-09890 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/28/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: --

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Thursday June 7 2022 at approximately 11:04AM, I, Inspector Randy Silver,  Conducted an on-sitere- inspection per document # 693506177.  Location: UPRR 43 Pan AM I30  Operator: KP Kauffman  API#:123-09890  County: Weld  While there, I observed shut in well site.  During this inspection the following possible compliance issues were observed:  Unused electric lines: Rule 606 Corrective action date of 2-5-22 see photo 3  Unused equipment: Rule 606 Corrective action date of 2-5-22 See photos 2,4  Mechanical issue: Rule 608 e Corrective action date of 7-8-22 see video  Weeds: Rule 606 Corrective action date of 8-7-22 See photos 2,4  Sign: Rule 605 g Corrective action date of 8-7-22 See photo 2  I called Mani Silva KPK supervisor at approx... 11:22AM and informed him of well head  leaking around tubing. He stated he would send someone out to repair. This is a  reinspection at time of inspection cement base and electric wiring has not been addressed.  Weather conditions: Dry  A follow up on this site inspection needs to be conducted to ensure the  compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	silverr	07/07/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403099047	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797404">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797404</a>
693507517	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797397</a>
693507518	video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797398">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797398</a>