

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/05/2022

Submitted Date:

07/08/2022

Document Number:

688312707**FIELD INSPECTION FORM**Loc ID 402845 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 24500Name of Operator: PADCO LLCAddress: 800 W 6TH STREET SUITE 1010City: LOS ANGELES State: CA Zip: 90017**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970) 768-5658	tcrumley@tcrumleypumpingse vice.com	Pumper
Richmond, Dan	(918) 630-9912	dan@dsrinc.net	Field Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236296	WELL	DA	05/22/1973	DA	121-08786	VENRICK D 1	DA

General Comment:

Field inspection to verify landowners finding of an open pipe in his field.

Submitted GPS coordinates: 40.021556 / -103.355874. Attached photos have: 40.02172, -103.35587 as GPS coordinates that are very close to those previously submitted by operator.

Documentation of plugging on 5/22/1973 is in the COGCC wellfile (see attached photos).

Corrective action is to cut 8 5/8" pipe ~4' below ground surface and install the required cap within 30 days (Aug 8, 2022) or prior to landowner planting wheat/in coordination with landowner.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment:

The 8 5/8" surface pipe for this well is at ground surface in a cultivated field. There is no cap on the pipe (see attached photos).

Corrective Action:

Per Rule 434a5, cut the 8 5/8" surface pipe (202' total depth per documentation) ~4' below ground surface in field and install required cap within 30 days.

Date: 08/08/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 236296 Type: WELL API Number: 121-08786 Status: DA Insp. Status: DA**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403099909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798260
688312708	PADCO Venrick D 1 (historic)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798257