

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2022

Submitted Date:

07/11/2022

Document Number:

702400690

FIELD INSPECTION FORMLoc ID 332876 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240916	WELL	PR	06/18/1976	OW	123-08704	UPRR 42 PAN AM AF 1	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil by the Gas Meter Run and at the load out line and valve on backside of crude oil tank		
Corrective Action:	Comply with Rule 912.a	Date:	08/11/2022
Type	WEEDS		
Comment:	weeds growing around WH, pump jack and TB areas		
Corrective Action:	Comply with Rule 606	Date:	07/25/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated angle iron and hog fence		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: barb wire			
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: appears plumbed to surface			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: Automation, Electric panel, meter box and transformers			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: electric motor			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: See Inspection Doc # 702400093 for related shared facilities and equipment.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspected FacilitiesFacility ID: 240916 Type: WELL API Number: 123-08704 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/27/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/11/2022 at approximately 1440 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location: UPRR 42 Pan AM AF 1.</p> <p>API #05-123-08704</p> <p>County: Weld.</p> <p>While there, I observed a wellsite and tank battery, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>606 Housekeeping: weeds growing around the WH, PJ and at the battery, CA date 7-25-2022.</p> <p>912.a Housekeeping: Stained soil by the Gas Meter Run and by the load out line and valve no the Crude oil tank, CA date 8-11-2022.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	07/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403101742	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800057
702400691	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800055