

Today's Date:	7/19/2022					
Well Name:	DOWLER 1B	Location:	Sec: 30	Twn: 034N	Rng: 009W	UL: K
API Number:	05.067.09496	Footage:	1763' FSL & 1811' FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0101	Bob Percell	
Meter #:	06633107		Pipeline:	HEC		
INC Number:	702500241	Agency:	COGCC	Inspector:	Alex Klink	
Type of INC:	Written	Photos Required:	Yes	Due Date:	7/27/2022	
Issue of Concern:	Comment: Trash on east edge of location (IMG 07). Corrective Action: Remove trash per rule 606.					
	Comment: Lube oil at wellhead has impacted surface material (IMG 04 and IMG 05). Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.					
	Comment: Discharge end of culvert near location entrance is full of gravel (IMG 06). Corrective Action: Maintain/repair required BMPs per Rule 1002.f.(2)C					





LAPLATA COUNTY ROAD 214
Hilcorp Energy Company

DWR
70949-F **DOWLER #1B**
LATITUDE 37.15959800° N(NAD27)
LONGITUDE 107 86920900° W
UNIT K SEC 30 T34N R09W
1763' FSL 1811' FWL
API # 05-067-09496-00
LEASE # FEE ELEV. 6566
LA PLATA COUNTY, COLORADO
EMERGENCY CONTACT (505) 324-5170 OR 911

Removed all trash around the well pad



Removed all impacted material and disposed of it properly



Cleaned out the landowner's culvert near the locations entrance.

