

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2022

Submitted Date:

07/13/2022

Document Number:

702500220**FIELD INSPECTION FORM**Loc ID 326331 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | sjninspections@ikavenergy.com | All SW field inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 216244 | WELL | PR | 04/01/2021 | GW | 067-07850 | KNIGHT D 1 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|--|
| Type | WELLHEAD | | |
| Comment: | Sign is beginning to deteriorate (IMG 01). | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Sound panels are unused (IMG 06). | | |
| Corrective Action: | Use or remove unused equipment per rule 606. | Date: | 09/12/2022 |
| Type | WEEDS | | |
| Comment: | Weeds beginning to encroach on produced water tank (IMG 05). | | |
| Corrective Action: | | Date: | |
| Type | STORAGE OF SUPL | | |
| Comment: | Land owner appears to be using location to store bales of hay (IMG 03 and IMG 04). No reclamation variance/surface owner waiver in well file. | | |
| Corrective Action: | Remove stored agricultural product from location and discourage activities by third parties or obtain approved variance. | Date: | 09/12/2022 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---|-------|--|
| Type | OTHER | | |
| Comment: | Produced water tank and pump control panel are enclosed by stock panel. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Ancillary equipment | # 6 | | corrective date |
| Comment: | Telemetry, pump control panel, electric panel, electric meter, electric cabinet, valve cluster pit. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 3 | | |
| Comment: | 2 2" lines from wellhead to separator, line from separator to produced water, line from separator to off location. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas meter calibration is within the last year. | | |

| | | | |
|---------------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric. | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead is accessible. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | Separator vent stack is screened properly. | | |
| Corrective Action: | | Date: | |
| Type: Progressive Cavity | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------------|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLs | PBV STEEL | | 37.172126,-107.627456 |
| Comment: | Partially buried produced water tank. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 95 bbl |
| Other (Type) | cone top |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|------------------|
| Earth | Inadequate | Walls Insufficient | Base Sufficient | Inadequate |
| Comment: | Berm height on west side is diminished and impacted by animal burrow (IMG 07). | | | |
| Corrective Action: | Maintain secondary containment per rule 603.o | | | Date: 08/12/2022 |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 216244 Type: WELL API Number: 067-07850 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 403104963 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5802567 |
| 702500221 | Photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5802564 |