

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21SESW

Location ID: 335230



Photo #7221 from entrance to location.



Photo #7223 Undesirable plant species in tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21SESW

Location ID: 335230



Photo #7224 Undesirable plant species in tank containment.



Photo #7226 Gully erosion occurring in access road ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21SESW

Location ID: 335230



Photo #7227 Gully erosion occurring in access road ditch.



Photo #7228 Gully erosion occurring in access road ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE-66S95W /21SESW

Location ID: 335230



Photo #7229 No velocity checks located in ditch.



Photo #7231 No velocity checks located in ditch.