

# Inspection Photos

API: 121-10095

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/21/2022



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing south toward the location. The access road travels thru the location to an active well site. The area out side of the road at the disturbed location has not been reclaimed. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 2.** Facing south toward the location. The access road travels thru the location to an active well site. The area out side of the road at the disturbed location has not been reclaimed. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 3.** Facing south at the location which has not been reclaimed and remains bare of crop growth. A 100 ft. tape measure shows the length of disturbance which goes beyond 100 ft. The red arrow points to an area planted to millet which has failed to grow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 4.** Facing west toward the location which remains with no crop growth. A 100 ft. tape measure shows the length of disturbance. The road travel thru the center location at the red line. There is approximately 50 ft. of disturbance with no crop growth at the west and east side of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 5.** Facing north toward the location. The location is slightly elevated from the surrounding crop fields and there is asphalt debris that remains thru the location shown within red circle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 6.** View of asphalt material found thru the location.



**Photo 7.** The soils throughout areas of the location are compacted. The shovel could not penetrate through the soil surface.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 8.** Facing north toward the location. The access road travels thru the location to an active well site. The area out side of the road at the disturbed location has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022

## Inspection Photos



**Photo 9.** Facing west toward the surround crop field consisting of harvested winter wheat.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/21/2022