

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2022

Submitted Date:

07/22/2022

Document Number:

702500265

FIELD INSPECTION FORM

 Loc ID 333828 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

2 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216107	WELL	PR	04/01/2019	CBM	067-07713	KRAJACK 43-27 1	PR
294380	WELL	PR	01/12/2016	GW	067-09483	KRAJACK 43-27 3	PR
294381	WELL	PR	01/14/2008	CBM	067-09484	KRAJACK 43-27 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign does not list capacity (IMG 04).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/21/2022

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	Oily residue from compressor trailer has impacted surface material (IMG 06).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	07/30/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	All equipment enclosed by stock panels.		
Corrective Action:		Date:	

Equipment:

Type:			corrective date
Vertical Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:		Date:	
Compressor	# 1		
Comment:	Compressor trailer		
Corrective Action:		Date:	
Bradenhead	# 3		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Gas Meter Run	# 3		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Linear rod pump		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Bales of hay are used as sound barrier for compressor trailer. (IMG 05).		
Corrective Action:			Date:
Type: Flow Line	# 10		
Comment:	3 3" and 3 2" lines from wellheads to separators, 3 lines from separators to produced water, 1 1" line from wellhead to gas generator.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry, gas generator skid		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 216107 Type: WELL API Number: 067-07713 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 294380 Type: WELL API Number: 067-09483 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 294381 Type: WELL API Number: 067-09484 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			
Ditches	Pass					
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403113280	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810082
702500268	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5810078