

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2022

Submitted Date:

08/01/2022

Document Number:

696304349**FIELD INSPECTION FORM**Loc ID 317532 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7800

Name of Operator: BEREN CORPORATION

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	316-337-8340	reynoldsr@berexco.com	
Hanes, Shawn		haness@berexco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433344	TANK BATTERY	AC	04/14/2009		-	MOYER 'A'-612N56W 29SESW	AC

General Comment:

This is a Tank Battery Inspection only.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical Tanks - 2 Tanks missing Labels; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/02/2022
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Oily Waste in Loadline Bucket; see photos		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	08/15/2022

Overall Good: ☐**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 7		corrective date
Comment:	7: Chemical pumps w/ drums, tanks & drip containment.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electrical Pump for Water Injection		
Corrective Action:		Date:	
Type: FWKO	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shares berm with the Crude Oil Tanks
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shares berm with the other Crude Oil Tanks
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLS	STEEL AST		40.980338,-103.661201

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	300 BBLs	FIBERGLASS AST		40.980504,-103.661013	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID: 433344	Type: TANK	API Number: -	Status: AC	Insp. Status: AC
Producing Well				
Comment:	Active Tank Battery and Waterflood Recovery Facility			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat: 40.979862Long: -103.660615Reference Point: SEOther: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: Produced WaterLined: NO

Pit ID:

Lat: 40.980121Long: -103.661084Reference Point: SEOther: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Date:

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		Date:
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: Lat: <u>40.980183</u> Long: <u>-103.660670</u>
Reference Point: <u>SE</u>	Other: _____	Length: _____ Width: _____
<u>Lining:</u>		
Liner Type:	Liner Condition:	
Comment:		
Corrective		Date:
<u>Fencing:</u>		
Fencing Type: <u>Livestock</u>	Fencing Condition: <u>Adequate</u>	
Comment:		
Corrective Action		Date:
<u>Netting:</u>		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>Multiple produced water pits. Foreman indicated only used for emergencies.</u>	
Corrective Action		Date:

COGCC Comments

Comment	User	Date
<u>Routine Field Inspection. Chemical Tanks missing Labels, Oily Waste at Loadline Bucket</u>	petrie	08/01/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304350	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5817388