

Inspection Photos
Location Name: Thacker 1
Location ID: 32931



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Ruts beginning to develop in access road



IMG 04

Trailer on location

