

Inspection Photos  
Location Name: Le Platt A 1  
Location ID: 325938



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**

**Lube oil has impacted surface material**



**IMG 04**

**Weeds beginning to encroach on wellhead**