

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2022

Submitted Date:

08/01/2022

Document Number:

702500307

FIELD INSPECTION FORM

Loc ID: 306891 Inspector Name: Klink, Alex On-Site Inspection: 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274170	WELL	PR	10/18/2004	CBM	067-08984	SMITH-WOLTER 2	PR

General Comment:
Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Lease Road:			
Type	Access		
comment:	Access road beginning to develop ruts (IMG 05).		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Pump jack enclosed by sound panels.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Produced water tank, separation equipment, and gas meter run enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	3" and 2" line from wellhead to separator, line from separator to produced water, 4" line from gas meter run to off location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	Electric	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.248342,-107.656708
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 274170 Type: WELL API Number: 067-08984 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					run on berm
Ditches	Pass					run on ditch
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
		Gravel	Pass			

Comment: Stormwater channel on northeast corner of location (IMG 03 and IMG 04). Channel is ~6" wide by ~3" deep, and deepens to ~1' wide by ~1' deep, extending to bottom of fill slope.

Stormwater channel ~6" wide and 6" deep near electric cabinet (IMG 06).

Facilities must be operated in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Corrective Action: **Install or repair/modify required BMPs per Rule 1002.f.(2)C.**

Date: 08/17/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500308	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5817958