

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2022

Submitted Date:

08/01/2022

Document Number:

702500317

FIELD INSPECTION FORMLoc ID 325931 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.co m	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215586	WELL	PR	09/01/2019	CBM	067-07191	THACKER 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Ruts beginning to develop in access road (IMG 03).			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				Date:
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Landowner is storing trailer on edge of location (IMG 04).			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Equipment is enclosed by stock panel.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 4			corrective date
Comment:	4" and 2" line from wellhead to separation equipment, 2" line from separation equipment to produced water off location, 2" line from gas meter run to off location.			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Separation equipment			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Last gas meter calibration: 7/14/21			
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).			Date: 09/02/2022
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:				Date:

Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Telemetry, pump control panel, electric meter, electric panel, valve cluster pit.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 215586	Type: WELL	API Number: 067-07191	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Ditches	Pass					
Berms	Pass					
Rip Rap	Pass					
Compaction	Pass					
Retention Ponds	Pass					
Check Dams	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500318	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5817963