

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2022

Submitted Date:

07/26/2022

Document Number:

702500281**FIELD INSPECTION FORM**Loc ID 320908 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295374	WELL	PR	11/19/2008	CBM	007-06246	CONLEY 7	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank capacity is not listed (IMG 05).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/25/2022

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds established at wellhead and around location (IMG 03 and IMG 04).		
Corrective Action:	Control weeds per rule 606.	Date:	08/02/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Pump jack enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	3" line from wellhead to separator, 1" line from wellhead to gas powered prime mover, line from separator to produced water		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	Gas meter calibration is within the last year.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Separator vent stack is screened properly	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		37.000655,-107.442738
Comment:	Above ground produced water tank				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Weeds established on secondary containment berm, affecting berm permeability (IMG 04).			
Corrective Action:	Control weeds on earth berms per rule 603.0 and 606.			Date: 08/02/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 295374 Type: WELL API Number: 007-06246 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 09/26/2017 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Last reported Bradenhead test: 9/26/201701/15/2022Corrective Action: Perform annual bradenhead test per rule 419.c

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403117601	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5813108
702500282	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5813105