

Inspection Photos

API: 071-07085

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022

Inspection Photos



Photo 1. Facing south toward the access road stream crossing. It appears a recent storm event had overtopped the crossing. The two culverts are not sufficient to handle storm events. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022

Inspection Photos



Photo 2. Facing south toward the access road stream crossing outlet side. There is no bank stabilization at the outlet side. Recent dozer work was performed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022

Inspection Photos



Photo 3. There are two culverts installed at the stream crossing. This appears to be inadequate as the prior cement culvert shown in the photo on the right had 3 large culverts.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing northwest along the side of the access road. All disturbed areas along the road side need to be seeded and stabilized. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022

Inspection Photos



Photo 5. Facing northwest along the side of the access road. All disturbed areas along the road side need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022

Inspection Photos



Photo 6. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 8/3/2022