

Inspection Photos

August 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335038

Location Name: Honea 19-05

Inspection Document #: 702800552

Garfield County, CO

Lot 2 Section 19 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



Photo 1. Photo taken from the east shows an overview of the Location.



Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



Photo 2. Photo taken from the east shows an overview of the western portion of the Location. Photo also shows the cut slope is unstabilized. Upon completion of construction, slopes must be stabilized.



Photo 3. Photo taken from the east shows an overview of the eastern portion of the Location.

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



Photo 4. Photo taken from the northeast shows a straw wattle installed around the perimeter of the topsoil stockpile has not been properly installed. The wattle has not been trenched and backfilled.



Photo 5. Photo taken from the northeast shows a straw wattle installed around the perimeter of the topsoil stockpile. Adjacent wattles have not been properly installed and wattles have not been trenched and backfilled.

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



Photo 6. Photo taken from the south shows a straw wattle installed around the perimeter of the topsoil stockpile is in disrepair and is not in proper functioning condition to protect the stockpile. Downslope sections of the wattle were not trenched and backfilled.



Photo 7. Refer to Photo 6 comment.

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



Photo 8. Photo taken from the east of the Location shows the perimeter stormwater diversion ditch. The channel shape has been properly constructed however, soil in the ditch is loose and unconsolidated, acting as a pollutant source. Velocity checks have been installed within the ditch.



Photo 9. Refer to Photo 8 comments.

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



8/8/22
+39.426354, -107.824010
318° NW

Photo 10. Photo taken from the west of the Location shows a sediment trap. The inlet and outlet to the trap have been installed with rip-rap and a geotextile lining.



8/8/22
+39.426425, -107.824087
110° E

Photo 11. Photo taken from the west of the Location shows soils of the fill slope are unstabilized. Upon completion of construction, slopes must be stabilized.

Inspection Photos
Location Name: Honea 19-05
Location ID: 335038



8/8/22
+39.425663,-107.822654
239° SW

Photo 12. Photo taken from the southeast shows plumeless thistle, a CO List B Noxious Weed found occasionally throughout the perimeter of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800552