

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403133872

Date Received:

08/11/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Aaron

aaron.trujillo@state.co.us

TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800552

Inspection Date: 08/08/2022

FIR Submit Date: 08/10/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335038

Location Name: Honea Number: 19-05 County: \_\_\_\_\_

Qtrqtr: Lot 2 Sec: 19 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.426341 Longitude: -107.822717

FACILITY - API Number: 05-045-00 Facility ID: 335038

Facility Name: Honea Number: 19-05

Qtrqtr: Lot 2 Sec: 19 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.426341 Longitude: -107.822717

CORRECTIVE ACTIONS:

1 CA# 163862

Corrective Action: Install or repair BMPs per Rule 1002.f.

Date: 08/12/2022

Response: CA COMPLETED

Date of Completion: 08/11/2022

Operator  
Comment:

As noted in Inspection Report Number 702800552, there were several locations identified where livestock / wildlife have disturbed and/or damaged the straw wattles (mostly around the topsoil stockpile) creating gaps, holes, and loosening stakes. Several locations were also identified where straw wattles were not properly installed. TEP storm water maintenance crews have repaired areas where the straw wattles were found to be damaged, disturbed, or not installed correctly. TEP will continue to conduct routine construction storm water inspections to identify areas where future maintenance of BMPs may be required.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please route to Anna O'Malley and Aaron Trujillo.

As noted in Inspection Report Number 702800552, there were several locations identified where livestock / wildlife have disturbed and/or damaged the straw wattles (mostly around the topsoil stockpile) creating gaps, holes, and loosening stakes. Several locations were also identified where straw wattles were not properly installed. TEP storm water maintenance crews have repaired areas where the straw wattles were found to be damaged, disturbed, or not installed correctly. TEP will continue to conduct routine construction storm water inspections to identify areas where future maintenance of BMPs may be required.

TEP has also scheduled weed sprayers to treat the Noxious Weeds noted at this location during this same inspection. The weeds will be treated prior to the 8/15/22 corrective action date. A separate FIRR will be submitted when this corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 8/11/2022 4:07:25 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files