

Inspection Photos

API: 061-06023

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 1. Drone aerial photo facing west toward the battery and wellsite. There is a remediation project in process.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 2. Facing southwest toward the tank battery facility. The tank was removed and soils have been excavated in this area. Remediation project: 20712



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 3. Facing west toward the tank battery facility. The tank was removed and soils have been excavated in this area. Remediation project: 20712



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 4. There are soil piles stored at the battery site. There appears to be oil contaminated soil present in the soil pile on the right.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 5. The berms around the soil piles are insufficient and need to be properly constructed and compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 6. Facing west toward the area where the spill occurred. Remediation project: 20712. Some areas have been excavated more than other areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 7. Located at the western side of the spill area. There is an excavated hole on this area approximately 12'x12'6". There are still areas of oil stained soils at the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 8. Facing northwest at the down gradient side of the spill area. There are no stormwater controls to prevent sediment movement off site. BMP's must be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 9. The one wire electric fence is inadequate to prevent livestock entry. The electric wire to the post will make the electric wire deficient.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 10. Facing southeast toward the remediation area. There are still areas of oil stained soil shown at red arrow. No stormwater controls are installed to prevent sediment movement offsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022

Inspection Photos



Photo 11. Drone aerial photo facing east toward the battery and remediation project.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 8/10/2022