

# Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022

## Inspection Photos



**Photo 1.** Facing north along the access road which has not been recontoured and reclaimed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022

## Inspection Photos



**Photo 2.** Facing northwest toward the former tank battery site located 300' southwest of the well site. The access road has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022



## Inspection Photos



**Photo 3.** Facing southwest toward the former tank battery site located 300' southwest of the well site. This area has been recontoured and pipe risers have been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022

## Inspection Photos



**Photo 4.** Facing south at the recontoured battery site. There are no stormwater controls installed down gradient and bare soils are susceptible to erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022



## Inspection Photos



**Photo 5.** Facing north toward the well site. The access road has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022

## Inspection Photos



**Photo 6.** Facing northeast toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to erosion. This area has been recontoured and decompacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 8/10/2022