

# Inspection Photos

API: 061-06020

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 1.** Facing west traveling to the location There has been recent topsoil hauled in along the flowline area. The wellsite is shown at top of photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 2.** Facing west toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 3.** The fence at the tank battery is inadequate and needs maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 4.** There is incomplete secondary containment at the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 5.** Facing toward the pumpjack. There is stormwater runoff transporting sediment offsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022

## Inspection Photos



**Photo 6.** There are signs of sediment movement offsite. BMP's need to be installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06020 - Date: 8/10/2022