

Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel



Photo #1 Sign at wellhead.

Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel



Photo #2 sign near wellhead.

Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel



Photo #3 overview of wellhead and excavated soil.



Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel

Photo #4 supply flowline from injection pump. It was told to COGCC that this was the point of failure, where line transitions from fiberglass to steel, at collar.



Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel

Photo #5 flowline



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel



Photo #6 excavation at flowline near injection well.



Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel

Photo #7 pipe on left of photo was coming out of the ground to well.



Inspection Photos
482698

Inspection Date: 8/8/2022
All Photos taken by Kris Neidel

Photo #8 Bradenhead access



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources