

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2022

Submitted Date:

08/16/2022

Document Number:

694500503

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 NEIDEL, KRIS 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 95520  
 Name of Operator: WESCO OPERATING INC  
 Address: 120 S DURBIN STREET  
 City: CASPER State: WY Zip: 82602
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
312860	LOCATION	AC			-	MAUDLIN GULCH UNIT-64N95W 27SWNW	EI
482698	SPILL OR RELEASE	AC	08/12/2022		-	Maudlin Gulch Unit #12	EI

**General Comment:**

on 8/8/2022 COGCC staff, Kris Neidel inspected spill 482698 at the Maudlin Gulch #12 injection well. The spill was reported by the operator. At the time of inspection the following was observed; no free fluid (spilled fluid) was present, the failed pipe had been excavated, the failure was observed and photo documented, it was told to COGCC by Wesco pumper that the spill was discovered during normal well checks, after the spill was discovered, the pumper went down to the pump to shut the pump in, it was told that the well was injecting below 200 psi, it was told to COGCC that no pressure was observed on the backside of the well. The spill was observed as fluid daylighting on the surface. Wesco has filed a Form 19 and has stated that they are collecting soil samples to confirm compliance with Table 915-1. No other equipment on location, other than IJ well. see attached photos.

**Inspected Facilities**

Facility ID: 312860 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 482698 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500504	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5831622">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5831622</a>