

Smith Wolter 2

Document number 702500307

Date completed 8/16/2022

Installed rock run outs where erosion channeling was beginning



Repaired road damage from channeling
Additional rock run out

