

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2022

Submitted Date:

08/18/2022

Document Number:

693701025**FIELD INSPECTION FORM**Loc ID 318999 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10575Name of Operator: 8 NORTH LLCAddress: 370 17TH STREET SUITE 5200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob		jevans@civiresources.com	
,		Inspections@civiresources.com	All Inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242672	WELL	PA	04/18/2022	OW	123-10463	SUSIE 11-9	EI
482448	SPILL OR RELEASE	CL	06/29/2022		-	Susie 11-9 Historical	EI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: 09/01/2022Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	snow fence around excavation has fallen down		
Corrective Action:	Maintain fencing at site	Date:	<u>09/01/2022</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	242672	Type:	WELL	API Number:	123-10463	Status:	PA	Insp. Status:	EI
Facility ID:	482448	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC inspection of Spill 482448 and Remediation Project 22270 for well and facility decommissioning. Operator reported historical release "exceedances were noted across the facility with TPH exceedances at the above ground storage tank and dump line". Operator has reported initial laboratory results on a Form 19 and submitted initial assessment results at the well on a Form 27 Supplemental. During the site inspection, several areas of excavation were observed with snow fence surrounding excavations and unidentified stockpiled materials placed adjacent. Excavations were full of water. Several monitoring wells are present at the location, possibly related to Remediation Project 4853.

Produced water pits were formerly closed under Remediation 4853 and 5471. The former produced water pit area has not reclaimed.

Corrective Action: As part of decommissioning and spill/release investigation, Operator shall investigation areas that have not successfully reclaimed, and prepare a reclamation plan to be submitted on a Form 27 Supplemental for Remediation Project 22270. Operator shall identify purpose of monitoring wells present on location.

Date: 09/22/2022

Operator shall submit a Form 27 Supplemental with current remediation status and assessment results by September 27, 2022)

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ **Wildlife Protection Devices (fired vessels):** _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701026	Susie11-9LocationPhotos8-17-2022	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833798