

Inspection Photos Location ID:312083



Well signs, including signs for PA wells



Hott 20-2 1 well not cut and capped



Inspection Photos

Location ID: 312083



Monument and parts stored in revegetation area. Portable toilet with no BMPs such as anchoring to prevent blow over or spill prevention.



Trash and debris

Inspection Photos
Location ID: 312083



Close up of trash/debris and fencing



Wood debris and food wrapper

Inspection Photos
Location ID: 312083



Production equipment from PA well not removed, unused parts



Produced water tank



Inspection Photos

Location ID:



Vertically staked wattles, not trenched in on north side of new disturbance



Looking south from PA well at new construction on different grade from original pad

Inspection Photos Location ID



Erosion channel that will run onto new disturbance



Erosion channel with no BMPs

Inspection Photos
Location ID: 312083



Wattle installation on south side of disturbance



BMPs installation appears inadequate to control run-off on south side of new disturbance

Inspection Photos
Location ID: 312083



Stake in SE corner labeled with “top soil”



Stake in NE corner labeled “top soil” and what appears to be top soil storage in a board flattened area on perimeter of new disturbance arewa

Inspection Photos
Location ID: 312083



Stormwater erosion at culvert on access road, no outlet protection BMPs



Erosion at culvert on access not inlet protection

Inspection Photos
Location ID: 312083



Erosion at culvert inlet on access road, improperly installed/maintained straw wattles



Erosion at culvert outlet on access

Inspection Photos
Location ID: 312083



Erosion at culvert outlet on access



Erosion along access and improperly installed/maintained straw wattles