

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2022

Submitted Date:

08/19/2022

Document Number:

700704522

## FIELD INSPECTION FORM

 Loc ID 335440 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Findings:**

- 10 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278953	WELL	PR	07/25/2005	GW	045-10961	STRANAHAN 21D-27-692	PR
278954	WELL	PR	12/20/2005	GW	045-10960	STRANAHAN 21B-27-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 8/17/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Stranahan 21B, at Location # 335440 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A (stored equipment) has not been completed from document # 700703012. FIRR documents # 402790442 and #402769650 states C/A has been completed. Therefore C/A date remains the same.

During this inspection the following possible compliance issues were observed:

1. Storage of equipment (ECD is disconnected from all lines)
2. Sediment migration from location at entrance of location

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: See storm water		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type CONTAINERS		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type OTHER		
	Comment: Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
	Type STORAGE OF SUPL		
	Comment: Storage of equipment (ECD is disconnected from all lines) C/A date remains the same from previous inspection (8/19/2021)		
Corrective Action:	Remove stored equipment		Date: 08/19/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
	Type WELLHEAD		
	Comment:		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	<a href="#">See stored equipment</a>		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Chemical tank in plastic containment</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 278953 Type: WELL API Number: 045-10961 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 278954 Type: WELL API Number: 045-10960 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [1. Sediment migration from location at entrance of location](#)

Corrective Action: **Install or repair required BMPs**

Date: 09/30/2022

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704527	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834840">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834840</a>