

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2022

Submitted Date:

08/17/2022

Document Number:

696304368**FIELD INSPECTION FORM**Loc ID 453567 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10670Name of Operator: MALLARD EXPLORATION LLCAddress: 1400 16TH STREET SUITE 300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**22 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mathews, Erin	970-302-6171	emathews@mallardexploratio n.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453560	WELL	PR	06/01/2022	LO	123-46202	Wigeon Fed 33-28-2HN	PR
453563	WELL	PR	06/01/2022	LO	123-46205	Wigeon Fed 33-28-1HN	PR
453564	WELL	PR	06/01/2022	LO	123-46206	Wigeon Fed 33-28-5HN	PR
453566	WELL	PR	06/01/2022	OW	123-46208	Wigeon Fed 33-28-8HN	PR
453568	WELL	PR	06/01/2022	OW	123-46209	Wigeon Fed 33-28-6HN	PR
453570	WELL	PR	06/01/2022	OW	123-46211	Wigeon Fed 33-28-7HN	PR
453571	WELL	PR	06/01/2022	LO	123-46212	Wigeon Fed 33-28-3HN	PR
453572	WELL	PR	06/01/2022	OW	123-46213	Wigeon Fed 33-28-4HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Compressor Drain Vault missing Labels - Content, Capacity and NFPA; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/19/2022
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash Dumpster is overflowing, see photos		
Corrective Action:	Comply with Rule 606	Date:	09/02/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead Parts on South end of Location. See photos		
Corrective Action:	Comply with Rule 606	Date:	09/02/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	Cooler		
Corrective Action:		Date:	

Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electrical and Automation Equipment		
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 210 BBLs	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares berm with the Crude Oil Tanks					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares berm with the Crude Oil Tanks					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	500 BBLs	STEEL AST		40.610370,-104.094710
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	453560	Type:	WELL	API Number:	123-46202	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453563	Type:	WELL	API Number:	123-46205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453564	Type:	WELL	API Number:	123-46206	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453566	Type:	WELL	API Number:	123-46208	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453568	Type:	WELL	API Number:	123-46209	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453570	Type:	WELL	API Number:	123-46211	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453571	Type:	WELL	API Number:	123-46212	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	453572	Type:	WELL	API Number:	123-46213	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection.	petrie	08/17/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403139466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832516
696304369	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832515