

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2022

Submitted Date:

08/25/2022

Document Number:

702500334**FIELD INSPECTION FORM**Loc ID 325149 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	505-326-2659	notices@rlbayless.com	All inspection
Thomas, John	505-326-2659	jthomas@rlbayless.com	all inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214125	WELL	PR	10/28/1963	GW	067-05436	SUNICAL 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Lease road beginning to develop ruts (IMG 06).			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	No tank label or placard present on eastern storage tank (IMG 05).			
Corrective Action:	Install sign to comply with Rule 605.f.			Date: 09/24/2022
Emergency Contact Number:				
Comment:	Emergency contact: 505-327-0880			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Empty chemical drum adjacent to well head is not in use (IMG 08). Metal panel on eastern edge of location is not in use (IMG 07).			
Corrective Action:	Unused equipment should be returned to service or stored off location per rule 606. If chemical drum is returned to service it must be placed on spill prevention per rule 1002.f.(2)B			Date: 09/24/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Deadman # & Marked	# 4			corrective date
Comment:	Rig anchor not marked properly (IMG 04). This is a CA from inspection doc#685302850			
Corrective Action:	Install proper guy line markers per Rule 1003.a			Date: 09/24/2022
Type: Horizontal Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Telemetry			
Corrective Action:				Date:
Type: Flow Line	# 7			
Comment:	2" line from wellhead to heated separator, 2" line from heated separator to additional separator, 2" line from separator to gas meter run, 2" line on intake and discharge of compressor, 2 lines from separators to produced water tanks. Not in use: 1" flow line at wellhead is not Locked out/Tagged out (IMG 03).			

Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)		Date:	09/08/2022
Type: Gas Meter Run	# 1			
Comment:	Gas meter calibration is within the last year.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	Separator vent stack is screened.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:			Date:	
Type: Compressor	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		PBV STEEL		37.106356,-107.853148	
Comment:	Partially buried produced water tank with steel mesh screen top.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	unlabeled	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		PBV STEEL		37.106400,-107.853252	
Comment:	Partially buried produced water tank with steel mesh screen top.					
Corrective Action:						
Date:						

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 120 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	214125	Type:	WELL	API Number:	067-05436	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500335	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839554