

KP Kauffman - COGCC Inspection Photos
Location: Rogers #1 Consolidation Flowline
Spill ID #482755 Date 08/24/2022



Rogers #1 flowline excavation at release point ; view south.



View of flowlines exposed in excavation at release point; (1) 4" carbon steel flowline (being repaired) with a bolted clamp over hole in line; (1) 16"-18" CS OLF (consolidation).

KP Kauffman - COGCC Inspection Photos
Location: Rogers #1 Consolidation Flowline
Spill ID #482755 Date 08/24/2022



View of flowlines exposed in west bellhole excavation during repairs; view NE along WCR 14.5



View of flowlines exposed in east bellhole excavation during repairs; view W along WCR 14.5