

Inspection Photos
Location Name: Xavier 1
Location ID: 325411



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Lube oil



IMG 04
Tank sign



IMG 05

Deteriorating paint



IMG 06

Wattles beginning to deteriorate